

Bulletin Number: ND-CYL-005

Date of Issue: June 7, 2010

Product Group:	Air Preparation	Actuators	Cylinders	Grippers	Vacuum / Sensors	Valves	Other	
Notice of Discontinuance								
Subject:	P5TT/P5TD Twin Rod Cylinder Discontinuance							

## Notice of Discontinuance of P5TT/P5TD Twin Rod Cylinder Series; Effective June 18, 2010

Effective June 18, 2010, Parker's P5TT/P5TD Twin Rod Cylinder Series will be discontinued due to low demand and high cost.



All open quotes will become invalid beyond June 18, 2010 and PDN will be supporting all last-time buys prior to June 18, 2010. Existing applications can be transitioned to the P5T series, which is the closest functional replacement for the P5TT/P5TD. Questions concerning P5TT/P5TD to P5T part number conversion should be directed to Applications Engineering.

Going forward, PDN is exploring lower cost alternative designs and products to fill this space in our product portfolio.

1)	The Product(s) Shown Above Will Be Discontinued Effective	June 18, 2010
2)	Orders For Complete Units Will Be Accepted Until	June 18, 2010
3)	Orders for Kits Will Be Accepted Until	December 15, 2015
4)	Last Date Returns Accepted	June 18. 2010



Parker Hannifin Corporation Pneumatic Division

135 Quadral Drive
Wadsworth, OH 44281 USA

Tel: 330 336 3511 Fax: 330 334 3335 Applications Engineering

Phone: 877 321 4PDN Option #2 E-mail: pdnapps@parker.com

Customer Support

Phone: 877 321 4PDN Option #1
E-mail: pdncustsvc@parker.com
Web site: www.parker.com/pneumatics